



Bear and Bison Resurfacing Cleaning Information for Countertops

Bear and Bison resurfaced Countertops should provide years of service when given the right care and maintenance.

- Wait 24 hours before using your resurfaced surface.
- Do NOT use harsh acids or bleach.
- Use only non-abrasive or liquid cleaners.

USE ONLY NON-ABRASIVE OR LIQUID CLEANERS - We recommend warm water and Dawn® dish soap. Other cleaners can be used, including, Lysol® Tub & Tile Cleaner, or Scrubbing Bubbles®.

USE ONLY NON-ABRASIVE MATERIALS – Such as a Sponge or Damp Cloth. Abrasive cleaning pads can dull or scratch a resurfaced surface. Examples of Abrasive cleaning pads are the steel wool pads.

ALWAYS RINSE THOROUGHLY after cleaning and wipe the surface **DRY**.

DO NOT USE ABRASIVE CLEANSERS, HARSH ACIDS OR CLEANERS THAT CONTAIN BLEACH! These materials can discolor or damage the surface causing premature wear. Example is Comet® or Clorox® bleach.

DO NOT ALLOW ANY CLEANERS OR CHEMICALS TO REMAIN ON THE SURFACE for an extended period of time before thoroughly rinsing.

DO NOT CUT DIRECTLY ON COUNTERTOPS, Please use cutting board.

DO NOT PLACE ANY HOT ITEMS DIRECTLY ON SURFACE.

TIPS: For best results, spray the surface with a liquid cleaner and let it sit for 3-5 minutes before cleaning with a damp cloth or non-abrasive sponge.